


Pendenza: tabella di conversione gradi/percentuale



a	b	%	gradi
100	100	100%	45
95	100	95%	44
90	100	90%	42
85	100	85%	40
80	100	80%	39
75	100	75%	37
70	100	70%	35
65	100	65%	33
60	100	60%	31
55	100	55%	29
50	100	50%	27
45	100	45%	24
40	100	40%	22
35	100	35%	19
30	100	30%	17
25	100	25%	14
20	100	20%	11
15	100	15%	9
10	100	10%	6
5	100	5%	3